THIS YEAR IN MOTOR

An index of the nearly 400 sales, management and service articles that have appeared in this magazine in 1969



SERVICE PROCEDURES

	Month	Page
ACCESSORIES		
VW Speedometer Cable Installation (F)	Mar.	29
Indicator-Light Replacement (S)	Mar.	80
Windshield-Washer Pump Removal (S)	Apr.	14
Corrects Chrysler Heater Trouble (F)	Apr.	75
10 Steps to Take When an Air-Conditioner Blows Its Cool	May	48
Overheating at Idle with Air-Conditioner (S)	May	72
Door Closing on Spot Coolers (S)	July	26
Operation of "Anti-Reverse" Odometer (S)	July	30
Trimming to Correct Radio Static (S)	Sept.	24
Horn and Speed Control Problem (S)	Nov.	20
Accessory Installation Tip (F)	Dec.	86
AXLES		
Lifting Models with Rear Stabilizer Bar (S)	Apr.	14
Truck Axle Stub Removal (F)	June	88
Truck Differential Remover (F)	Sept.	76
Rear-Axle Bearing Removal (S)	Dec.	12
BRAKES		
Why Not Service Truck Brakes?	Jan.	34
Bleeds Ford Truck Brakes (F)	Jan.	43
New Lining Corrects Chatter (S)	Jan.	66
Ford Brake Spring Installation (F)	Feb.	108
Retains GM Brake Cable (F)	Mar.	29
Retracts Caliper Pistons (F)	Mar.	29
High Brake-Pedal Effort (S)	Apr.	16
Power-Brake Push-Rod Adjustment (S)	May	72
New Overload Spring for Automotive Brake Adjuster (S)	June	22
Why Overhauling Ford Brakes Must Be a Custom Job	June	64
There's $3.1 Billion Worth of Brake Service Driving Around	June	68
Uncover Antiskid Control System Failures Fast	Sept.	70
Brake-Disc Refinish (S)	Oct.	40
Power-Brake Pedal Effort (S)	Oct.	42
Servicing Toyota Brakes	Oct.	49
17 Key Steps to Disc-Brake Service	Oct.	56
Now You Can Turn Disc-Brake Rotors	Nov.	56
Corvette Disc-Brake Noise (F)	Nov.	84
Disc-Brake Squeal (S)	Dec.	12
Parking-Brake Cable Assembly (S)	Dec.	14
Balancing Wheels on Cars with Disc Brakes (S)	Dec.	14
COOLING SYSTEM		
Thermostat Opening Change (S)	Apr.	14
Radiator Hose Removal (F)	May	9
Getting to the Heart of the Matter	May	51
Overheating at Idle With Air-Conditioner (S)	May	72
Straightens Radiator Fittings (F)	Sept.	74
ELECTRICAL SYSTEM		
Find Circuit Protectors Fast	Jan.	28
Wear Check on Distributor Loads (F)	Jan.	42
Headlight Spring Installation (F)	Jan.	43
Battery Cable Connection (S)	Jan.	62
Turn Signal Switch Installation (F)	Feb.	108
Window Motor Service Tips (F)	Feb.	112
Chevrolet Indicator Light Symptoms (F)	Feb.	112
Distributor-Shaft End Play (S)	Feb.	114
Taillamp Repair Kit Available (S)	Feb.	118
Faster Lamp Bulb Replacement	Mar.	58
Automatic Dimmer Stays Dipped (S)	Mar.	80
Procedure for Removing Alternator (S)	Apr.	16
Servicing 1969 Spark Plugs and Cables (S)	Apr.	16
Soldering Electrical Connections (F)	Apr.	75
Tests Ignition Bypass Resistors (F)	Apr.	75
Test Light Locates Shorts (F)	Apr.	76
Door Vacuum Leak Detector (F)	May	9
When Capacitor-Discharge Ignition Systems Falter	May	56
Starting Motor Noise on V-6 (F)	May	70
Super-Lite Bulb Replacement (F)	May	70
Ignition Timing Indicator (S)	May	72
Moves Inoperative Power Seat (F)	June	12
Distributor Pigtail Replacement (F)	June	87
Frees Stuck Light Lens (F)	June	88
Quick Check on Alternator (F)	July	9
Taillamp Ground on 1969 Model (S)	Aug.	26
Repair of Horn Switch on Steering-Wheel Rim (S)	Aug.	26
Rotor Gap Voltage Increase (S)	Aug.	30
Testing Alternator with a 'Scope	Aug.	44
5 Foolproof Tests to Check Ignition Primary Resistance	Aug.	48
Ford Headight-Switch Knob Installation (F)	Aug.	81
Spark Plug Removal (S)	Sept.	24
Repairs Stripped Headlight Adjuster (F)	Oct.	28
Distributor Wrench Modification (F)	Oct.	28
ENGINE		
Ford Lifter Removal (F)	Jan.	43
Cold Engine Loading with Monojet Carburetor (S)	Jan.	58
Rough Idle from Camshaft Wear (S)	Jan.	58
Stops Corvair Engine Rattle (F)	Feb.	112
Valve Lifter Replacement (S)	Feb.	118
Aids Valve Adjustment (F)	Mar.	28
Corvair Engine Removal (F)	Mar.	29
What's Happened to the Piston Engine	Mar.	49
Engine Overhaul Part I: How to Get Started	Mar.	61
Engine Overhaul: Cylinder Balance Testing	Mar.	64
Oversize Value-Guide Hole (S)	Mar.	78
Piston Installation Tool (F)	Mar.	89
Delcotron Drive-Belt Adjustment (S)	Apr.	14
Rocker Arm Interference (S)	Apr.	16
Valve-Spring Change (S)	June	22
Identifying 1969 Engines Fast	June	56
Broken Dipstick Tube Removal (F)	June	87
Rambler Flex-Plate Alignment (F)	June	87
Engine Replacement Tip (F)	June	88
Valve Seal Installer (F)	July	8
Aids Valve Lifter Removal (F)	July	9
Engine Overhaul, Part II: Working on the Valves	July	50
Engine Overhaul Profitable Specialty for Oklahoma Shop	July	50
New Rear Crankshaft Seal (S)	Aug.	30
Testing Alternators with a Scope	Aug.	44
Tracking Down PCV Failure	Aug.	50
Oil Burning: How to Read the Signals	Aug.	60
Locates Engine Noise on Pontiac (F)	Aug.	81
Detonation Knock on 318 and 383 Engines (S)	Sept.	24

THIS YEAR IN MOTOR

An index of the nearly 400 sales, management and service articles that have appeared in this magazine in 1969



SERVICE PROCEDURES

	Month	Page
ACCESSORIES		
VW Speedometer Cable Installation (F)	Mar.	29
Indicator-Light Replacement (S)	Mar.	80
Windshield-Washer Pump Removal (S)	Apr.	14
Corrects Chrysler Heater Trouble (F)	Apr.	75
10 Steps to Take When an Air-Conditioner Blows Its Cool	May	48
Overheating at Idle with Air-Conditioner (S)	May	72
Door Closing on Spot Coolers (S)	July	26
Operation of "Anti-Reverse" Odometer (S)	July	30
Trimming to Correct Radio Static (S)	Sept.	24
Horn and Speed Control Problem (S)	Nov.	20
Accessory Installation Tip (F)	Dec.	86
AXLES		
Lifting Models with Rear Stabilizer Bar (S)	Apr.	14
Truck Axle Stub Removal (F)	June	88
Truck Differential Remover (F)	Sept.	76
Rear-Axle Bearing Removal (S)	Dec.	12
BRAKES		
Why Not Service Truck Brakes?	Jan.	34
Bleeds Ford Truck Brakes (F)	Jan.	43
New Lining Corrects Chatter (S)	Jan.	66
Ford Brake Spring Installation (F)	Feb.	108
Retains GM Brake Cable (F)	Mar.	29
Retracts Caliper Pistons (F)	Mar.	29
High Brake-Pedal Effort (S)	Apr.	16
Power-Brake Push-Rod Adjustment (S)	May	72
New Overload Spring for Automotive Brake Adjuster (S)	June	22
Why Overhauling Ford Brakes Must Be a Custom Job	June	64
There's $3.1 Billion Worth of Brake Service Driving Around	June	68
Uncover Antiskid Control System Failures Fast	Sept.	70
Brake-Disc Refinish (S)	Oct.	40
Power-Brake Pedal Effort (S)	Oct.	42
Servicing Toyota Brakes	Oct.	49
17 Key Steps to Disc-Brake Service	Oct.	56
Now You Can Turn Disc-Brake Rotors	Nov.	56
Corvette Disc-Brake Noise (F)	Nov.	84
Disc-Brake Squeal (S)	Dec.	12
Parking-Brake Cable Assembly (S)	Dec.	14
Balancing Wheels on Cars with Disc Brakes (S)	Dec.	14
COOLING SYSTEM		
Thermostat Opening Change (S)	Apr.	14
Radiator Hose Removal (F)	May	9
Getting to the Heart of the Matter	May	51
Overheating at Idle With Air-Conditioner (S)	May	72
Straightens Radiator Fittings (F)	Sept.	74
ELECTRICAL SYSTEM		
Find Circuit Protectors Fast	Jan.	28
Wear Check on Distributor Loads (F)	Jan.	42
Headlight Spring Installation (F)	Jan.	43
Battery Cable Connection (S)	Jan.	62
Turn Signal Switch Installation (F)	Feb.	108
Window Motor Service Tips (F)	Feb.	112
Chevrolet Indicator Light Symptoms (F)	Feb.	112
Distributor-Shaft End Play (S)	Feb.	114
Taillamp Repair Kit Available (S)	Feb.	118
Faster Lamp Bulb Replacement	Mar.	58
Automatic Dimmer Stays Dipped (S)	Mar.	80
Procedure for Removing Alternator (S)	Apr.	16
Servicing 1969 Spark Plugs and Cables (S)	Apr.	16
Soldering Electrical Connections (F)	Apr.	75
Tests Ignition Bypass Resistors (F)	Apr.	75
Test Light Locates Shorts (F)	Apr.	76
Door Vacuum Leak Detector (F)	May	9
When Capacitor-Discharge Ignition Systems Falter	May	56
Starting Motor Noise on V-6 (F)	May	70
Super-Lite Bulb Replacement (F)	May	70
Ignition Timing Indicator (S)	May	72
Moves Inoperative Power Seat (F)	June	12
Distributor Pigtail Replacement (F)	June	87
Frees Stuck Light Lens (F)	June	88
Quick Check on Alternator (F)	July	9
Taillamp Ground on 1969 Model (S)	Aug.	26
Repair of Horn Switch on Steering-Wheel Rim (S)	Aug.	26
Rotor Gap Voltage Increase (S)	Aug.	30
Testing Alternator with a 'Scope	Aug.	44
5 Foolproof Tests to Check Ignition Primary Resistance	Aug.	48
Ford Headight-Switch Knob Installation (F)	Aug.	81
Spark Plug Removal (S)	Sept.	24
Repairs Stripped Headlight Adjuster (F)	Oct.	28
Distributor Wrench Modification (F)	Oct.	28
ENGINE		
Ford Lifter Removal (F)	Jan.	43
Cold Engine Loading with Monojet Carburetor (S)	Jan.	58
Rough Idle from Camshaft Wear (S)	Jan.	58
Stops Corvair Engine Rattle (F)	Feb.	112
Valve Lifter Replacement (S)	Feb.	118
Aids Valve Adjustment (F)	Mar.	28
Corvair Engine Removal (F)	Mar.	29
What's Happened to the Piston Engine	Mar.	49
Engine Overhaul Part I: How to Get Started	Mar.	61
Engine Overhaul: Cylinder Balance Testing	Mar.	64
Oversize Value-Guide Hole (S)	Mar.	78
Piston Installation Tool (F)	Mar.	89
Delcotron Drive-Belt Adjustment (S)	Apr.	14
Rocker Arm Interference (S)	Apr.	16
Valve-Spring Change (S)	June	22
Identifying 1969 Engines Fast	June	56
Broken Dipstick Tube Removal (F)	June	87
Rambler Flex-Plate Alignment (F)	June	87
Engine Replacement Tip (F)	June	88
Valve Seal Installer (F)	July	8
Aids Valve Lifter Removal (F)	July	9
Engine Overhaul, Part II: Working on the Valves	July	50
Engine Overhaul Profitable Specialty for Oklahoma Shop	July	50
New Rear Crankshaft Seal (S)	Aug.	30
Testing Alternators with a Scope	Aug.	44
Tracking Down PCV Failure	Aug.	50
Oil Burning: How to Read the Signals	Aug.	60
Locates Engine Noise on Pontiac (F)	Aug.	81
Detonation Knock on 318 and 383 Engines (S)	Sept.	24









	Month	Page
Engine Doesn't Crank (S)	Nov.	20
Handling Hood on Engine Removal (F)	Nov.	86
Steel Head Gasket for 428 cu. in. V-8 (S)	Dec.	14
Carelessness Can Kill Engine Bearings	Dec.	46
Core-Plug Installation (F)	Dec.	84
EXHAUST SYSTEM		
Pipe Clamp Gauge (F)	May	8
When Imports Need New Mufflers, Tailpipes	July	44
EXHAUST EMISSION CONTROL		
Don't Overlook Smog-Control Service	Feb.	85
SAE Pushes Smog Controls	Mar.	56
Fast Guide to Smog-Control Systems	July	70
Tracking Down PCV Failure	Aug.	50
False Reading from Exhaust Analyzer (F)	Nov.	86
How to Use the New Infrared Exhaust Analyzers	Dec.	44
FRONT END, STEERING		
Servicing GM's New Locking Steering Column	Jan.	31
VW Kingpin Bushing Installation (F)	Feb.	108
Low Riding Height Causes Alignment Troubles (S)	Mar.	80
Replace Truck Kingpins in 12 Easy Steps	Apr.	63
Steering-Gear Cover O-Ring Replacement (S)	June	20
Check for Bent Ball-Joint Stud (F)	July	8
Tie-Rod Timesaver (F)	July	8
Steering Column Lock-Cylinder Removal (S)	July	26
Front-End Adjustment (S)	July	30
Don't Sell Wheel Alignment, Sell "Front-End Tune-Up"	July	47
Steering-Pump Belt Adjustment (S)	Oct.	40
New Front-Wheel Bearing Adjustment (S)	Nov.	24
Control Arm Bushing Installer (F)	Nov.	84
Ball-Joint Installation (S)	Dec.	14
Balancing Wheels on Cars with Disc Brakes (S)	Dec.	14
Power-Steering Pump Belt Adjustment (F)	Dec.	84
FUEL SYSTEM		
Rich Condition on Warm-Up (F)	Jan.	42
Cold Engine Loading with Monojet Carburetor (S)	Jan.	58
Fuel Gauge Reading (S)	Jan.	62
Fuel Gauge Removal on 1969s (S)	Feb.	114
Correcting Flat Spot on '69 Chevrolet (F)	Mar.	28
Filter Stops Sticking Choke (S)	Mar.	78
Adjustment of 1968 Metering Rods (S)	Mar.	78
Fuel-Gauge Replacement (S)	Mar.	80
Aids Idle Adjustment (S)	May	8
Sticking Choke Causes Hard Start (S)	June	20
Chevrolet Fuel-Pump Installation (F)	June	87
Fuel Tank Filter (S)	July	30
Anchoring Screws on Rochester Carburetor (S)	Aug.	26
Monojet Carburetor Gasket (S)	Aug.	30
Rambler Poor-Performance Problem (F)	Aug.	81
Fuel Supply for Road Service (F)	Oct.	27
Secures In-Line Hose Connection (F)	Oct.	27
Detent Cable Adjustment Check (S)	Nov.	20
New Idle Adjustment	Nov.	24
Removal of Truck Fuel Gauge Sender (F)	Nov.	86
False Reading from Exhaust Analyzer (F)	Nov.	86
LUBRICATION		
Spin-On Filter Removal (F)	Feb.	108
Oil Pan Removal (F)	Apr.	76
Broken Dipstick Tube Removal (F)	June	87
Oil Burning: How to Read the Signals	Aug.	60
Oil-Pan Dent Repair (F)	Aug.	82
Easy Way to Take Off Opel Pan (F)	Sept.	76
ROAD SERVICE		
Lift Points for '70 Cars	Nov.	62
Jack Points for '70 Cars	Nov.	64
How to Start and Tow the '70s	Dec.	37
SUSPENSION		
Rear Shock Removal on GM Cars (F)	Jan.	42
Stops Chrysler Shock Rattle (F)	Mar.	28
Flanged Insulator in Stabilizer Bar (S)	Oct.	42
Control-Arm Bushing Installer (F)	Nov.	84
TRANSMISSION, CLUTCH		
Stops Transmission Breather-Pipe Leak (F)	Jan.	42
Stops Falcon Shift Lever Shake (F)	Jan.	72
Governor Check for Delayed Upshift (S)	Feb.	114
Service Changes on Automatic Stick-Shift Transmission (S)	Feb.	118
Jetaway Clutch Installation (F)	Mar.	28
Governor-Pipe Installation (F)	Mar.	89
Manual-Shaft Seal Replacement (F)	May	9
Four-Speed Manual Transmission Disassembly (S)	May	72
Neutral Switch Adjustment (S)	June	20
Special Mounting Bolt for Transmission (S)	June	22
GMC Truck Transmission Tip (F)	July	8
Hurst Shift-Lever Removal (S)	Sept.	22
Stops Transmission Linkage Rattle (S)	Sept.	24
Cleaning Welded Torque Converter (F)	Sept.	74
Detent Cable Adjustment Check (S)	Nov.	20
Solves Shift Problem on Ford (F)	Dec.	86
WHEELS, TIRES		
Brake Spinning Rear Wheels Gradually (S)	Jan.	58
Balancing P05 Option Wheel Assemblies (S)	Jan.	62
Truck Wheel Installer (F)	July	9
On-Car Wheel Balancing with Front Discs (S)	Sept.	22
Get that Wheel-Nut Torque Right!	Dec.	52
BODY AND FRAME		
Start with the Right Tools	Jan.	26
Hood Whistling Noise (S)	Jan.	66
Opening Inoperative Tailgate Window (S)	Jan.	66
Window Glass Sealant (S)	Jan.	66
Filing Close Contours (F)	Jan.	72
Release Frozen Door Catch (F)	Jan.	72

[CONTINUED ON PAGE 58

(S) = Service Slants
(F) = Fix It

THIS YEAR *continued*





	Month	Page
Hood and Lid Alignment (F)	Jan.	72
Secure Panel Repair (F)	Jan.	72
Push-Button Adjustment on Outside Door Handle (S)	Feb.	123
Rear-Door Glass Loose in Channel (S)	Feb.	123
Complete Front Suspension Repair	Mar.	53
Painting Tip on Metallics (F)	Mar.	84
Molding Installation Tip (F)	Mar.	84
Chevrolet Molding Replacement (F)	Mar.	84
Faster Dent Repair (F)	Mar.	84
Speeds Wheel Painting (F)	Mar.	84
How to Repair Fiberglass Fenders and Hoods	Apr.	59
Drilling Holes for Nameplates, Emblems (F)	Apr.	118
Drilling Stainless Steel (F)	Apr.	118
Loose Ash Tray (S)	Apr.	118
Rotate Calking Material Stock (S)	Apr.	118
Sprays Repaired Parts (F)	May	8
Door-Handle Clip Installation (F)	May	10
Lighter Tips (F)	May	10
Change in Door Lock (S)	May	10
Loose Ash Tray (S)	May	10
Power Is Key to Collision Repair	May	53
Molding Clip Installation (F)	June	12
Moves Inoperative Power Seat (F)	June	12
Nameplate Letter Replacement (S)	June	12
Grille Repair Parts (S)	June	12
Invisible "Mold Patch" Restores Vinyl Top	June	58
Portable Drill Press (F)	July	11
Head Restraint Removal (S)	July	11
TABCO a Year Later	July	40
Replacement of Broken Weld Studs (S)	Aug.	8
Bumper Removal Procedure Shortened (S)	Aug.	8
Anchors Striker on Truck Door (F)	Aug.	8
Method of Opening Tailgate in Emergency (S)	Sept.	10
Front-Wheelhouse Removal (S)	Sept.	10
Molding Clip Replacement (F)	Sept.	10
Quick Quarter Job on Rambler	Sept.	67
Door-Striker Adjustment (S)	Oct.	30
Bumper-Face Bar Removal (S)	Oct.	30
Outer Door-Panel Replacement (F)	Oct.	30
Tool for Bolted Glass (F)	Oct.	30
VW Mini Gets Nose Job	Nov.	9
Front Wheelhouse Removal (S)	Nov.	76
Door-Glass Noise Correction (S)	Nov.	76
Chevy II Ash Tray Repair (F)	Nov.	76
Replacing Rear Quarter Panel on Javelin	Dec.	41
Window Regulator Motor Removal (S)	Dec.	68
Heater Motor Removal (S)	Dec.	68
Painting Recessed Letters (F)	Dec.	68

NEW CAR SERVICE

	Month	Page
Service on the '69s	Feb.	55
Tune-Up	Feb.	56
Engine	Feb.	57
Brakes	Feb.	58
Starter, Charging System, Lights	Feb.	60
Rear Axle, Driveline	Feb.	62
Body, Frame	Feb.	64
Front End, Steering, Suspension	Feb.	67
Comfort and Safety Accessories	Feb.	69
Transmission	Feb.	71
Exhaust System	Feb.	72
Cooling System	Feb.	74
Quick Service on the New Maverick	June	54
Major Specifications of the '70 Models	Sept.	64
Hood Latch, Gas Filler Cap Locations on '70 Cars	Oct.	54

RACING AND PERFORMANCE

	Month	Page
First Electric-Car Record	Jan.	14
NASCAR Tracks Where the Action Is	Feb.	22
Car Rallies	Mar.	32
Dune Buggies	Apr.	20
High Performance: Big Today . . . Bigger Tomorrow	Apr.	49
Does Racing Improve Detroit Cars?	Apr.	52
How Racers Rate Speed Laws	Apr.	54
What About Shop Interest in High Performance?	Apr.	55
You Have to Talk Their Language	Apr.	56
Swinging Sebring	May	14
End of the Road for Turbine?	May	62
1969 Program and Scorecard	June	8
The South Invades the North	July	12
Sports Car Club Celebrates 25th Anniversary	Aug.	10
Safety on the Track	Sept.	14
The Racetrack Boom	Oct.	22
Can-Am Makes the Going Great	Oct.	52
What's Different About a High-Performance Shop?	Oct.	60
The Greatest Grand Prix	Nov.	38
What Makes a High-Performance Car Different?	Nov.	106

EQUIPMENT HINTS

	Month	Page
Anchors Droplight Wire in Handle (F)	Aug.	82
Fuel Supply for Road Service (F)	Oct.	27
Distributor-Wrench Modification (F)	Oct.	28

SERVICE MANAGEMENT

	Month	Page
Business Climate	Jan.	24
Repairman Liable for Others' Work	Jan.	50
3 R's at Brevard Are Now: Reading, 'Riting, and Repair	Mar.	66
Better Mechanics Mean Better Business	Mar.	69
What About Shop Interest in High Performance?	Mar.	55
Why Women Customers Are Different	Apr.	62
"We Are Trying to Glamorize the Mechanic"	May	59
Computer Is Service "Brain" at Fleet Garage	May	82
Free Car-Care Clinics Turn Ladies into Customers	June	50
Licensing vs. Certification	June	62
Auto Lab Bets $1 Million on Scientific Service	June	76
Engine Overhaul Profitable Specialty for Oklahoma Shop	July	50
Productivity, Part I: Minding Your Shop's P.Q.	July	56
Are You Wasting Money on Dual-Coverage?	July	101
It Pays to Be Beautiful	Aug.	18
Creating a $1 Million Body Shop	Aug.	51
Productivity, Part II: Tools and Equipment	Aug.	54







	Month	Page
Dynamic New Leader of IGO	Aug.	57
The Service Market in the '70s	Sept.	6
What's Behind the Fast-Growing Paint and Body Business	Oct.	46
Productivity, Part III: Closing the Equipment Gap	Oct.	60
Truck Service: Are You in the Picture	Nov.	45
Truck Service: How the Demand Is Being Met	Nov.	48
What's Behind American Way's Push for 5,000 Collision Shops	Nov.	59
Volume Doubles in Award-Winning Shop	Nov.	104
Giving Gets the Most from Your Men	Dec.	50
Lets Computers Do the Bookkeeping	Dec.	90

SERVICE SALES

	Month	Page
Forecast '69	Jan.	21
Eight Ways to Increase Your Profits	Jan.	54
69 Selling Ideas for '69	Feb.	70
Citizen-Band Radio Turns Customers On	Feb.	76
It Pays to Sell to Married Women	Feb.	77
Sell Tires Like a Specialist	Feb.	78
Antique Cars Build Strong Image	Feb.	79
Don't Sell Him a Tune-Up, Sell Him a Package	Feb.	80
Give Customers a Front-End Suspension Test	Feb.	81
Sell the Complete Brake Job	Feb.	82
Batteries Boost Business	Feb.	83
Beauty Aids Sweeten Station's Profit	Feb.	84
What to Do About Silent Customers	Mar.	20
High Performance: Big Today . . . Bigger Tomorrow	Apr.	49
You Have to Talk their Language to Sell Speed and Custom	Apr.	56
Cash In with Safety-Check	Apr.	58
What to Do with Superior Customer	Apr.	112
Four Ways to Close a Sale	May	24
Make Summer Service a Custom Job	May	45
Don't Take a Vacation From Summer Service Sales	June	67
There's $3.1 Billion Worth of Brake Service Driving Around	June	68
Give Your Customer a Little Extra	July	60
How to Hold Your Customers' Interest	Aug.	72
Gain Customer's Confidence	Sept.	78
21 Shop Ideas That Really Work	Sept.	125
Get Big Results with Small Ads	Sept.	126
Make Your Signs "Talk"	Sept.	126
Let the Phone Help You Sell	Sept.	127
Clowning Around Balloons Volume	Sept.	128
String of Signs Tells Message	Sept.	128
Woman's Touch Is Successful	Sept.	129
Radio Advertising Turns Up Volume	Sept.	129
He's Always Giving Something Away	Sept.	130
Direct Mail Bridges Customer Gap	Sept.	131
He Sells His Mother-in-Law	Oct.	16
How to Sell Pre-Winter Service	Oct.	68
Sell Extra Service for City Trucks	Nov.	51

TBA MERCHANDISING

	Month	Page
The ABC of Selling 365 Tires A Year	Jan.	37
How He Sold 400 Cases of Additives in Three Weeks	Mar.	68
Sell 12 Sealed Beams and 40 Bulbs a Week	Apr.	73
It Pays to Specialize	May	28
Stereo Tape Units Turn On Profits	June	6
Vibrators Smooth Way to Shock Sales	July	24
Flair for Promotion Earning Station Owner $20,000 Annually	July	55
He Sells $30,000 Worth of Tires a Year	Aug.	22
How He Doubled Fan Belt Sales in a Year	Sept.	28
5 Point Program for Wiper Blade Success	Oct.	18
Makes Four Air-Filter Sales a Day Routine	Nov.	28

(S) = Service Slants
(F) = Fix It

TECHNICAL, DESIGN DEVELOPMENT

	Month	Page
What Turbines Are Up To Now	Jan.	38
Throwing New Light on Headlights	Jan.	44
What's Happened to the Piston Engine?	Mar.	49
SAE Pushes Smog Control	Mar.	56
More Uses Coming for Aluminum?	June	80
Will New Cars Be Easier to Repair?	July	37
On a Clear Day GM Can See Tomorrow's Cars	Aug.	41
What's New in Ford's New $100 Million Dollar Engine?	Nov.	53

CAR REGISTRATION

	Month	Page
Vehicle Registrations Top 100 Million Mark	July	58

NEW CAR DESCRIPTIONS

	Month	Page
American Motors '70	Sept.	63
American Motors Hornet	Aug.	46
American Motors SC/Rambler	Apr.	115
Buick '70	Sept.	56
Cadillac '70	Sept.	60
Chevrolet '70	Sept.	57
Chevrolet Blazer	Apr.	115
Chrysler '70	Sept.	50
Dodge '70	Sept.	48
Ford '70	Sept.	52
Ford Maverick	Apr.	114
International Scout Aristocrat	June	85
International Scout 800A	Apr.	116
Lincoln '70	Sept.	55
Mercury '70	Sept.	54
Oldsmobile '70	Sept.	59
Opel GT	Apr.	115
Peugeot 504	Dec.	90
Plymouth '70	Sept.	46
Plymouth Road Runner	Dec.	94
Pontiac '70	Sept.	61
Pontiac H-P Firebird	Apr.	114
SAAB B-4	Jan.	112
SAAB 99	Apr.	102
SAAB 99 Automatic	Dec.	65
Toyota Corolla	Apr.	99
Volkswagen '70	Nov.	83
World's Cars on Stage	May	68